SCULPTACLAY SAFETY GUIDELINES



Use on a protected work surface. Wax may stain porous materials.



Wash hands after handling. Avoid contact with eyes and mouth.



Do not ingest.



Intended for industrial and professional use only. Not certified for use under age 12.

SAFE HEATING GUIDELINES

Warning: Always allow wax to cool before handling.



Wear heat-resistant gloves if using heated tools.




Warm gently to no more than 120°F (48°C).



Do not use on open flames or high-temperature tools.



Do not leave heated or hot tools unattended.



Work in a ventilated space and do not inhale fumes if heating occurs.



Dispose waste properly. Do not wash wax down drains.

For safety inquiries or technical support, email: sales-usa@precizioned.com For saftey data sheets (SDS) please visit https://sculptaclay.com/safety-info/